



- 0** Zero line
- G** Burr height
- h** Workpiece thickness
- t** C'sinking depth
- S** Clearance distance



After spindle stop (Speed = 0, blade retracted), rapid traverse through the workpiece.


Position:  $h + G + S$



Activate spindle clockwise. Select correct activation speed to extend blade.


Attention: Dwell time 1 sec. at least. Increase speed to working speed. Switch coolant on.

Position:  $h + G + S$




Machine workpiece backwards in working speed.

Position:  $h - t$



Travel out of countersink in rapid traverse. Switch off coolant.


Position:  $h + G + S$




Stop the spindle. Select speed rate = 0 to retract blade.

Attention: Dwell time 1 sec. at least.


Position:  $h + G + S$



With stopped spindle (speed rate = 0) and in rapid traverse withdraw the tool from the workpiece.




- 0** Zero line
- G** Burr height
- h** Workpiece thickness
- t** C'sinking depth
- S** Clearance distance




Activate spindle clockwise with retraction speed (speed = 1900 rev./min. minimum). The blade retracts. Travel through workpiece with rotating spindle and in rapid traverse.

Position:  $h + G + S$




Stop the spindle. Dwell time 1 sec. at least. Switch on coolant. Set the speed to working speed.

Position:  $h + G + S$




Machine the workpiece backwards in working speed and with working feed.

Position:  $h - t$



Travel out of countersink in rapid traverse. Switch off coolant.


Position:  $h + G + S$



Retract blade by increasing spindle speed to 1900 rev./min. minimum.

Attention: Dwell time 1 sec. at least.

Position:  $h + G + S$



Travel through workpiece with retraction speed (Speed rate 1900 rev./min. minimum) and in rapid traverse and with retracted blade.